


CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM		Page 1 of 8
Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO	Date: 08/25/2008
Test Type: Smoke	Ground Condition: Dry: <input checked="" type="checkbox"/> Damp: <input type="checkbox"/> Wet: <input type="checkbox"/>	Supervisor: E.R. Crew: 03
Manhole ID: S17K__040MH	Test ID: 1029-552	Notifications Made: <input checked="" type="checkbox"/> X Residents, Fire, 311
Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)		



[illegible]

CITY OF BALTIMORE
SMOKE TESTING OBSERVATION SUMMARY
LOW LEVEL SEWERSHED
BALTIMORE CITY PROJECT 1029
REI/DRAYCO

Unique Test ID: 552	Date: 08/25/2008	Basin: LL - 44	Manhole ID: S17K__040MH
Defect No: OB01	Supervisor: E.R.	Crew: 03	Dye Test Recommended: N
Location: 2511 MCHENRY ST.			
Source Type: 03 Cleanout		Sector: 02 Private	
Location: 05 Sidewalk		Severity: 03 Moderate	Drainage Area: 2
Comments: SMOKE COMING FROM BELOW GRADE CLEANOUT ON SIDEWALK.			

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01
Filename: 1029-552_OB01-01.jpg

CITY OF BALTIMORE
SMOKE TESTING OBSERVATION SUMMARY
LOW LEVEL SEWERSHED
BALTIMORE CITY PROJECT 1029
REI/DRAYCO

Unique Test ID: 552	Date: 08/25/2008	Basin: LL - 44	Manhole ID: S17K__040MH
Defect No: OB02	Supervisor: E.R.	Crew: 03	Dye Test Recommended: N
Location: 2513 MCHENRY ST.			
Source Type: 02 Service Line		Sector: 02 Private	
Location: 06 Curb		Severity: 03 Moderate	
		Drainage Area: 20	
Comments: SMOKE COMING FROM BELOW CONCRETE SLAB AROUND STEPS AND GATE.			

SMOKE TEST PHOTOGRAPHS



Photograph No: OB02-01
Filename: 1029-552_OB02-01.jpg

CITY OF BALTIMORE
SMOKE TESTING OBSERVATION SUMMARY
LOW LEVEL SEWERSHED
BALTIMORE CITY PROJECT 1029
REI/DRAYCO

Unique Test ID: 552	Date: 08/25/2008	Basin: LL - 44	Manhole ID: S17K__040MH
Defect No: OB03	Supervisor: E.R.	Crew: 03	Dye Test Recommended: N
Location: 2538 FREDERICK RD.			
Source Type: 02 Service Line		Sector: 02 Private	
Location: 08 Yard - Back		Severity: 03 Moderate	Drainage Area: 10
Comments: SMOKE COMING FROM BELOW GRADE HOLES AROUND CLEANOUT IN BACKYARD.			

SMOKE TEST PHOTOGRAPHS



Photograph No: OB03-01
Filename: 1029-552_OB03-01.jpg

CITY OF BALTIMORE
SMOKE TESTING OBSERVATION SUMMARY
LOW LEVEL SEWERSHED
BALTIMORE CITY PROJECT 1029
REI/DRAYCO

Unique Test ID: 552	Date: 08/25/2008	Basin: LL - 44	Manhole ID: S17K__040MH
Defect No: OB04	Supervisor: E.R.	Crew: 03	Dye Test Recommended: N
Location: 2548 FREDERICK RD.			
Source Type: 02 Service Line		Sector: 02 Private	
Location: 08 Yard - Back		Severity: 03 Moderate	Drainage Area: 40
Comments: SMOKE COMING FROM AREA AROUND BASE OF TREE IN CENTER OF PICTURE ON OPPOSITE SIDE OF THE FENCE.			

SMOKE TEST PHOTOGRAPHS



Photograph No: OB04-01
Filename: 1029-552_OB04-01.jpg

CITY OF BALTIMORE
SMOKE TESTING OBSERVATION SUMMARY
LOW LEVELSEWERSHED
BALTIMORE CITY PROJECT 1029
REI/DRAYCO

Unique Test ID: 552	Date: 08/25/2008	Basin: LL - 44	Manhole ID: S17K__040MH
Defect No: OB05	Supervisor: E.R.	Crew: 03	Dye Test Recommended: N
Location: 319 S. FRANKLINTOWN RD.			
Source Type: 09 Building Interior		Sector: 02 Private	
Location: 14 Other		Severity: 04 Major	
		Drainage Area: 0	
Comments: HEAVY SMOKE COMING FROM INTERIOR OF BUILDING AT 319 S. FRANKLINTOWN RD.			

SMOKE TEST PHOTOGRAPHS



Photograph No: OB05-01
Filename: 1029-552_OB05-01.jpg

CITY OF BALTIMORE
SMOKE TESTING OBSERVATION SUMMARY
LOW LEVEL SEWERSHED
BALTIMORE CITY PROJECT 1029
REI/DRAYCO

Unique Test ID: 552	Date: 08/25/2008	Basin: LL - 44	Manhole ID: S17K__040MH
Defect No: OB06	Supervisor: E.R.	Crew: 03	Dye Test Recommended: N
Location: 321 S. FRANKLINTOWN RD.			
Source Type: 02 Service Line		Sector: 02 Private	
Location: 06 Curb		Severity: 03 Moderate	Drainage Area: 50
Comments: SMOKE COMING FROM CURB ALONG ALLEY BEHIND PROPERTY.			

SMOKE TEST PHOTOGRAPHS



Photograph No: OB06-01
Filename: 1029-552_OB06-01.jpg